

Safety recommendation no. 455

Date of the publication	01.05.2013
Number of the final report	2156
Safety deficit	On 16 February 2011 a Citation C525 overshot the end of runway 07 at Grenchen regional airport (LSZG) and collided with obstacles. The accident is attributable to the fact that the expected acceleration during the take-off roll was not achieved because the parking brake was set. The investigation identified the absence of a warning device indicating a set parking brake on initiation of the take-off roll as a contributory factor.
Safety recommendation	The Federal Office of Civil Aviation (FOCA) and the European Aviation Safety Agency respectively should develop a technical solution together with the licensing authority for the Cessna C525 type, which warns the crew when the take-off roll is initiated with the parking brake set.
Addressees	BAZL Bundesamt für Zivilluftfahrt
Investigation report concerning the safety recommendation	Schlussbericht Final report

Tel.: +41 58 466 33 00, Fax.: +41 58 463 33 01 info@sust.admin.ch

www.sust.admin.ch