



Swiss Confederation

Notification

We inform you about an accident of an aircraft registered in Spain, which occurred in the Czech Republic:

Place, date and time: Runway 24R LKPM, 28 June 2023, 13:34 LT

Aircraft

Registration Mark: EC-LQH
Type: Pilatus, PC-6/B2-H4
Operator: Jump Aviation, SL
Owner: Jump Aviation, SL

Pilot: 1

Flight:

Flight rules: Visual Flight Rules (VFR)
Type of operation: unknown
Point of departure: Příbram airport (LKPM), Czech Republic
Point of landing: Příbram airport (LKPM), Czech Republic

Damage:

Crew: None
Passengers: None
Thirds: None
Aircraft: Slightly damaged
Ground: None

Short description: According to the pilot's statement he lost directional control during cross-wind landing, the aircraft veered to the right, the left wing dropped and as a result the left balance rod fixed on the outer part of the left aileron caught the grass. In the final stage, the outer part of the left aileron was torn off and this part of the wing was deformed.

Remarks: An investigation has been opened by the Air Accidents Investigation Institute AAIL, Czech Republic

Bern, 3 August 2023