



Safety recommendation no. 67

Date of the publication	25.08.2015
Number of the final report	2013011002
Safety deficit	On Thursday 10 January 2013 at 07:34, the S11 train No. 19126 from Schaffhausen collided at entry point 25 in Neuhausen with the S33, train No. 20330, travelling from Winterthur to Schaffhausen. The collision caused injury to 17 persons and substantial material damage. The distance between the exit signal and the danger spot was too short to bring a normally accelerating train to a standstill before the point of collision. Neuhausen did not have a departure hindrance system.
Safety recommendation	The FOT should arrange for stations with the same or similar operating conditions to be equipped with departure hindrance function.
Stage of the implementation	Partially implemented.
Investigation report concerning the safety recommendation	<u>Schlussbericht</u>