



Swiss Confederation

## Notification

This report contains short preliminary information about a serious incident, without pretension to completeness and without conclusions. An investigation is in progress by the Swiss Transportation Safety Investigation Board.

**Place, date and time:** Geneva airport (LSGG) (GE), 10 December 2021, 07:00 LT

**Aircraft**

**Registration Mark:** 9H-VCL

**Type:** Bombardier Canada, Challenger CL350

**Operator:** Vistajet Ltd., Skypark Business Centre, Luqa LQA 4000, Malta

**Owner:** Yunwei Corporate Jet Leasing Company Ltd.,  
2, Grand Canal Square, Grand Canal Harbour, Dublin 2, Ireland

**Pilots:** 2

**Cabin crew:** 1

**Passengers:** 5

**Flight:**

**Flight rules:** Instrument Flight Rules - IFR

**Type of operation:** Commercial

**Point of departure:** Geneva airport (LSGG)

**Point of landing:** Wien-Schwechat airport (LOWW)

**Ground Support Vehicles**

**Callsign:** Eskimo 1, Eskimo 2, Eskimo 11

**Type:** Boschung Jetbroom 9000 Snow Plug

**Operator:** Genève Aéroport, Postbox 100, CH-1215 Genève 15

**Crew:** 1 Driver each

**Damage:**

**Crew:** None

**Passengers:** None

**Thirds:** None

**Aircraft:** None

**Ground:** None

**Short description:** Runway incursion by snow plug vehicles whilst an aircraft was taking off.

Berne, 15.12.2021