



Swiss Confederation

## Notification

This report contains short preliminary information about an accident, without pretension to completeness and without conclusions. An investigation is in progress by the Swiss Transportation Safety Investigation Board.

**Place, date and time:** Vierwaldstättersee, north of Bürgenstock (LU),  
28 July 2025, 09:45 LT

### Aircraft

**Registration Mark:** D-FSAM  
**Type:** Daher, TBM-940  
**Operator:** Privat  
**Owner:** Privat

**Pilot:** 1

**Passengers:** 1

### Flight:

**Flight rules:** VFR, with planned IFR-joining  
**Type of operation:** Private  
**Point of departure:** Buochs Airfield (LSZC), Switzerland  
**Point of landing:** Burg Feuerstein (EDQE), Germany

### Damage:

**Crew:** None  
**Passengers:** Injured  
**Thirds:** None  
**Aircraft:** Seriously damaged  
**Ground:** Not yet known

**Short description:** The single-engine turboprop aircraft took off from Buochs (LSZC), Switzerland, for a flight to Burg Feuerstein (EDQE) in Germany. It departed from runway 24 under visual flight rules with a planned transition to instrument flight rules later on. After approximately three minutes of flight time, the aircraft crashed into Lake Lucerne north of Bürgenstock and sank. The pilot was uninjured; the passenger suffered injuries.

Berne, 31 July 2025