Aviation Division

Swiss Confederation

NOTIFICATION

This report contains short preliminary information about a serious incident, without pretension to completeness and without conclusions. An investigation is in progress by the Swiss Transportation Safety Investigation Board.

Place, date and time: Buochs (LSZC), 21 December 2016, approx. 15:00 LT

Aircraft:

Registration Mark: EC-IBY

Type: PC-6 H2/B4

Operator: Air Compluto, Aeródromo Don Quijote s/n, E-45870 Lillo

(Toledo)

Owner: Air Compluto, Aeródromo Don Quijote s/n, E-45870 Lillo

(Toledo)

Pilots:

CMD: Spanish citizen, year of birth 1979

F/O: Spanish citizen, year of birth 1977

Cabin crew: 0
Passengers: 0

Flight:

Flight rules: VFR

Type of operation: private **Point Departure:** LFLU **Point of landing:** LSZC

Damage:

Crew: 0

Passengers: 0

Thirds: 0

Aircraft: None Ground: None

Short description of the

serious incident:

The crew decided to execute a VFR approach in Buochs (LSZC) with an observed visibility of approximately 4 km

and a closed cloud base of about 600 ft/GND. The aircraft has been observed in a seemingly uncontrolled attitude below the cloud layer. Subsequently the aircraft landed on

the airfield.