



Swiss Confederation

Notification

We inform you about an accident between an aircraft registered in Switzerland and an aircraft registered in France which occurred in France:

Place, date and time: Taxiway, Béziers (LFMU), 21 May 2022, 13:15 LT

Aircraft 1

Registration Mark: F-GPHL
Type: Robin DR 400-120
Operator: unknown
Owner: unknown

Pilot: 1

Passengers: 2

Flight:

Flight rules: unknown
Type of operation: unknown
Point of departure: Béziers (LFMU)
Point of landing: Béziers (LFMU)

Damage:

Crew: None
Passengers: None
Thirds: None
Aircraft: Destroyed
Ground: None

Aircraft 2

Registration Mark: HB-GAC
Type: Beech Aircraft Corporation, C18S
Operator: B 18 AG, Rigackerstrasse 24, 5610 Wohlen AG
Owner: B 18 AG, Rigackerstrasse 24, 5610 Wohlen AG

Pilot: 1

Flight:

Flight rules: unknown
Type of operation: unknown



Point of departure: Béziers (LFMU)
Point of landing: unknown

Damage:

Crew: None
Passengers: None
Thirds: None
Aircraft: Substantial damage
Ground: None

Short description of the accident: During taxi before departure, collision of aircraft 2 with a DR400 at holding point A.

Remarks: An investigation has been opened by the BEA France (www.bea.aero)

Bern, 26th July 2022