

NOTIFICATION OF AN INCIDENT

We inform you about an incident of an aircraft registered in Switzerland which occurred in (Germany):

Place, date, time: Munich Airport, 25.03.2005, 07:36 UTC

Aircraft:

Registration: HB-IXU
Type: BAE 146 – RJ100
Operator: Swiss International Airlines, Postfach, 4002 Basel
Owner: MELIK Mobilien Verwaltung, Postfach, 4002 Basel

Pilot: 2

Others: 2 cabin crew, 83 pax

Flight:

Type of operation: Sceduled flight
Point of departure: Zürich
Point of intended landing: Prag

Injuries and damages:

Pilot: none
Passengers: none
Aircraft: none
Other: none

Description of incident: During climb to cruise, the elevator needs increasing input forces to be moved. The crew decided to divert to Munich Int. Airport. On the approach to MUC below FL100, the forces for moving the elevator become normal.

Remarks: An investigation has been opened by the German Federal Bureau of Aircraft Accident Investigation.