



## NOTIFICATION

This report contains short preliminary information about a serious incident, without pretension to completeness and without conclusions. An investigation is in progress by the Swiss Transportation Safety Investigation Board.

**Place, date and time:** Zurich airport, 10<sup>th</sup> March 2016, 16:11 UTC

### Aircraft:

**Registration Mark:** HB-IYT

**Type:** AVRO 146-RJ100

**Operator:** Swiss Global Air Lines AG, Malzgasse 15, 4052 Basel

**Registered Owner:** Triangle Regional Aircraft Leasing Limited  
1 Bishop Square, St Albans Road West  
AL10 9NE Hatfield Hertfordshire, Great Britain

### Pilots:

**CMD:** Swiss citizen, 1966

**F/O:** German citizen, 1991

**Cabin crew:** 2

**Passengers:** 86

### Flight:

**Flight rules:** IFR

**Type of operation:** Commercial (Scheduled Flight)

**Point Departure:** Zurich (LSZH)

**Destination:** Geneva (LSGG)

### Damage:

**Crew:** None

**Passengers:** None

**Thirds:** None

**Aircraft:** Engine no. 2 damaged

**Ground:** None

**Short description of the serious incident:** The flight crew aborted the takeoff ground roll due to an engine fire warning. Flying sparks could be observed exiting from engine no. 2. The engine was shut down and its fire suppression system was activated. After examination by the fire service, the aircraft could be taxied back on stand for a normal disembarkation.