



NOTIFICATION

This report contains short preliminary information about a serious incident, without pretension to completeness and without conclusions. An investigation is in progress by the Swiss Accident Investigation Board.

Place, date and time: Inbound Zurich (Reims Ctl), 21.11.2014, 12:03 UTC

Aircraft:

Registration Mark: HB-JHB
Type: A330-343
Operator: Swiss International Air Lines Ltd.
Owner: Swiss International Air Lines Ltd.

Pilots: 2

Passengers: Not yet known

Flight:

Flight rules: IFR
Type of operation: Scheduled flight
Point and time of departure: Newark KEWR, 05:48 UTC
Point of landing: Zurich LSZH

Damage:

Crew: None
Passengers: None
Thirds: None
Aircraft: None
Ground: None

Short description of the After descent initiation from FL 390, cabin pressurization malfunctions occurred. An emergency descent was performed and the aircraft landed uneventfully at destination.