



Swiss Confederation

## Notification

This report contains short preliminary information about an accident, without pretension to completeness and without conclusions. An investigation is in progress by the Swiss Transportation Safety Investigation Board.

**Place, date and time:** Geneva Airport (LSGG), 23 June 2021, 19:20 LT

### Aircraft

**Registration Mark:** M-ISTY

**Type:** Gulfstream Aerospace LP, G280

**Operator:** INEOS Aviation, Hawkslease Chapel Lane, Lyndhurst Hampshire, SO43 7FG

**Owner:** Hampshire Aviation LLP, Hawkslease Chapel Lane, Lyndhurst Hampshire United Kingdom SO43 7FG

**Pilot:** 2

**Cabin crew:** 1

**Passengers:** 9

### Flight:

**Flight rules:** Instrument Flight Rules (IFR)

**Type of operation:** Private

**Point of departure:** Nice Côte d'Azur Aéroport (LFMN)

**Point of landing:** Genève Aéroport (LSGG)

### Damage:

**Crew:** None

**Passengers:** None

**Thirds:** None

**Aircraft:** Substantial

**Ground:** None

**Short description:** After a hard landing on runway 22, the aircraft showed deformations on the right wing root and was leaking jet fuel.

Bern, 23 June 2021