

Investigation Bureau

Swiss Confederation

Notification

We inform you about an accident of an aircraft registered in Canada which occurred in Quebec, Canada.

Place, date and time: Kangirsuk Airport (CYAS), Quebec, in Canada,

25 March 2024, 20:15 UTC

Aircraft

Registration Mark: C-FYMN

Type: Pilatus Aircraft Ltd, PC-12/47

Operator: Chrono Aviation Inc.
Owner: Chrono Aviation Inc.

Pilots: 2

Passengers: 4

Flight:

Flight rules: Instrument flight rules (IFR)

Type of operation:

Point of departure: Quaqtaq Airport (CYHA), Quebec, Canada **Point of landing:** Kangirsuk Airport (CYAS), Quebec, Canada

Damage:

Crew: None
Passengers: None
Thirds: None

Aircraft: Seriously damaged

Ground: None

Short description: C-FYMN, a Chrono Aviation incorporation Pilatus PC-12/47 was operat-

ing as NDL987 under instrument flight rules from Quaqtaq Airport (CYHA), Québec, Canada to Kangirsuk Airport (CYAS), Québec, Canada. During landing in a crosswind (reported winds of 280 true at 26 knots with gusts to 36 knots), the crew selected reverse thrust but nothing happened. Approximately 5 seconds later, as the pilot was about to apply power for a go around, the reverse thrust activated at maximum. The crew lost control and the plane veered sideways from the runway at approximately 20 knots and came to rest in the snow. There were no in-

juries. The plane suffered damage.

Remarks: The Transportation Safety Board of Canada has opened an investiga-

tion. (https://www.tsb.gc.ca)

Bern, 26th April 2024

Tel.: +41 58 466 33 00, Fax.: +41 58 466 33 01

info@sust.admin.ch www.sust.admin.ch