

Investigation Bureau

Swiss Confederation

## Notification

This report contains short preliminary information about an accident, without pretension to completeness and without conclusions. An investigation is in progress by the Swiss Transportation Safety Investigation Board.

Place, date and time: Aircraft		La Punt Chamues-ch (GR), 17 March 2025, 17:22 LT
	<b>Registration Mark:</b>	D-EXIK
	Туре:	SST Flugtechnik GmbH, Extra 400
	Operator:	BA Services I/S, Nøddegangen 6, DK-2840 Holte
	Owner:	BA Services I/S, Nøddegangen 6, DK-2840 Holte
Pilot:		1
Passengers:		2
Flight:		
	Flight rules:	Visual Flight Rules (VFR)
	Type of operation:	Private
	Point of departure:	Airport Samedan (LSZS)
	Point of landing:	Airport Copenhagen-Roskilde (EKRK)
Damage:		
	Pilot:	Fatally injured
	Passengers:	Fatally injured
	Thirds:	None
	Aircraft:	Destroyed
	Ground:	Sight damage
Short description:		After taking off on runway 03, the single-engine piston aircraft crashed in an inhabited area on the northern edge of the village of La Punt Chamues-ch and completely burnt out.

Bern, 25.03.2025