



Notification of Cessation of an Investigation

This is to inform you of the cessation of the following investigation:

Place, date and time: Airport Berne-Belp BE, 2 September 2003, 15:04 LT

Aircraft:

Registration Mark: HB-IAQ
Type: Falcon 900 EX
Operator: Swiss Jet AG, 8058 Zurich
Owner: B.G. Investments Ltd., Bermuda, P.O. Box, Hamilton

Pilot 1: Swiss citizen, born 1950

Pilot 2: Swiss citizen, born 1956

Passengers: 11

Flight:

Flight rules: IFR
Type of operation: Government flight
Point and time of departure: Lissabon LPPT, 10:55 LT
Point of landing: Berne-Belp

Short description of the incident: After landing, smoke and smell appeared in cockpit and passenger cabin.

Reason for the cessation: A turbo-ventilator was found to be the source of smoke and smell. An indepth investigation was carried out which revealed that a fatigue failure of a heating inside the turbo-ventilator caused some lubricant to evaporate and produce the smoke and smell observed. As the risk of fire could be excluded and no other danger was perceptible, the criterion for a severe incident does not exist.