

Investigation Board

Swiss Confederation

Notification

This report contains short preliminary information about a serious incident, without pretension to completeness and without conclusions. An investigation is in progress by the Swiss Transportation Safety Investigation Board.

Place, date and time:		Zurich Airport (LSZH) (ZH), 14 November 2023, 19:00 LT
Aircraft		
	Registration Mark:	HB-JZR
	Туре:	Airbus S.A.S., A320-214
	Operator:	EasyJet Switzerland SA, route de l'Aéroport 5, Case postale 831, 1215 Genève 15 Aéroport
	Owner:	AWAS 4034 Limited, c/o Alkers Corporate Service limited, 87 Mary Street, 1-9005 George Town Grand Cayman
Flight crew:		2
Cabin crew:		4
Passengers:		187
Flight:		
	Flight rules:	Instrument Flight Rules (IFR)
	Type of opera- tion:	Scheduled
	Point of depar- ture:	Nice Airport (LFMN), France
	Point of landing:	Geneva Airport (LSGG)
Damage:		
	Crew:	None
	Passengers:	None
	Thirds:	None
	Aircraft:	None
	Ground:	None
Short description:		After declaring an emergency due to low fuel, the airliner landed at Zurich Airport. The amount of fuel remaining after landing was below the final reserve fuel.

Berne, 23 November 2023

Swiss Transportation Safety Investigation Board STSB CH - 3003 Bern Tel.: +41 58 466 33 00, Fax.: +41 58 466 33 01 info@sust.admin.ch www.sust.admin.ch