

NOTIFICATION OF AN ACCIDENT

We inform you about an incident of an aircraft registred in Switzerland which occurred in (France):

Place, date, time: Lac Léman, near Saint Gingolph/F, 12.07.2003, 13.45 LT

Aircraft:

Registration: HB-UVF
Type: Bücker Bü 131 APM
Operator: AéCS Section de la Côte, Aérodrome, 1197 Prangins
Owner: AéCS Section de la Côte, Aérodrome, 1197 Prangins

Pilot: Swiss citizen, 1952

Others: 1 Passenger

Flight:

Type of operation: Private, VFR
Point of departure: Prangins
Point of intended landing: Prangins

Injuries and damages:

Pilot: Injured
Passengers: Killed
Aircraft: Destroyed and sunk
Other: None

Description of accident: Collision with the surface during a low pass near a boat.

Remarks: An investigation will be conducted by the BEA France